ROYAL FLUSH

WAR DEPART

REPORT OF AIRCRAFT ACCIDENT

(1) Place ... AAF STATION 123 AIRCRAFT: (4) Type and model .. B 24 J Organisation: (7)

		-	The Reservoir	LIBORREL		_			
(10)	NAME (Last name first)	RATING	SERLAL NO.	Rare	PERSONNEL. CLASS	BRANCE	Alta Fonce on	RESULT TO	Use o
P	MC. CARPRY, WITTIAM B.	(18)	(18)	(14)	(15)	(16)	(17)	(18)	Panaces (19)
CP	MORFORD, ROBERT W.	CP	0-795459	let It	1092	AC	8th	Home	No
H	STRAND . GEORGE E.	-	0-703080	780 FP	1092	AC .	8th	Mome /	No
B	BUTLER, JOHN R.	. B	0=702010	24 IN	1035	AC		Mone	No
E	POLAKOFF, LECNARD (NMI)	R.	12135033	. S/90T	748	AC	Beb.	None	No
RO.	MIXON . GERLAND G.	. RQ.	.39836613	s/30T	757	AC	8th	Hone I	No
2	MURTZ. LOWELL P.	0	12185660	SOT	71.8	AC	Sth	Mone!	Ho
2	APPLEBY . GEORGE C.	G	20129398	307	611	AC	8th		No
3	SINICOS, CUS D	G.	36237837	SOT	612	AC	8th		No
									Ro
				· · · · · · · · · · · · · · · · · · ·					

PILOT CHARGED WITH ACCIDENT (20) MC CARTHY WILLIAM (Last name) (First name) (21) C-795459 (22) 8th

Original rating (33) Pilot (34) h. Jen 43 Present rating (35) Pilot

FIRST PILOT HOURS: (at the time of this ac

(38) This type. 220:25 (42) Instrument time last 6 m (39) This model (43) Instrument time last 30 hays

(40) Last 90 days ... (44) Night time last 6 month

795 155 ... (48) Night time last 30 day AIRCRAFT DAMAGE DAMAGE (46) Aircraft Salvage (47) Engine(s)

5. milesa. Surface, wind NNE at 9 MPH

Training

(56) Nature of accident Take-off accident. No D and 2 props rem away on take-off.

(87) Cause of accident 75% Pilot error. 25% material failures

(55) Form 54 being submitted.

DESCRIPTION OF ACCIDENT

citref narrative of accident. Include statement of responsibility and recommendations for action to prevent repetition

Lt MC CARTHY in A/C B 2h 44-0291 on 30 May 4h while starting to take-Off for a practice mission had the propellors on #1 and #2 engines rum away.

On the pre-take-off run-up the engines checked normal also the props sheck through normal. The A/C was them taxied onto the R/W and the power was applied for take-off. When the A/C had gained about 70 MPH \$1 prop started running away. Shortly after this #2 prop began to run away. It MC CAPTHY tried to control toggle switch which had no effect on controlling the props. No attempt was made to use the prop feathering mechanism to help stabilize the props. At this time the A/C was in the air with an airspeed of 120 MPH. Lt MC CAPTHY decided to cut the power and lend the A/C and try to stop it on the remainder of the R/W. However, having only 1300 feet of #/W left he was unable to bring A/C to stop on the R/W and ren off the end onto rough ground which tore the landing gear off and completely wreaked the A/Ca .

The recommendations are that the prop governors of all new A/C be tested for correct settings on the acceptance checks. Also, that the pilots try using feathering mechanism to help control a runsway prope

> JOHN A. HENSLER Major. AC



STATISHENT OF

let Lieutement William P. MC CAFFRY, MC. 0-795459, 7534 Bomb Sq. 458th Bomb Gp (H), AMF Station 123, AFO 558.

"On Tuesday, 30 May kh, I took off on a training flights I flow in the right hand seat of Aft kh-0291, B 24 J, so as to better fly formation in #3 postition. A pre-cakeoff check sheesed everything to be assumil-

On take-off, which ecourred at about 1210, it started normally until we had enhieved about 70 MPHs. At this time, \$F\$ Prop started to rm eavy. I watched for a second to make sure it was not due to run and then applied corrective action on the toggle switche. The prop continued to increase in RPMs. At this time, when \$F\$ had run eavy I elected \$Hs^2\$, and \$F\$ once it RPMs. At this time, when \$F\$ had run eavy I cleated \$Hs^2\$, and \$F\$ once the started in \$F\$ and \$F\$ were clay. The maximum reading on \$F\$ was about 3350s. When prop did not come back

Them \$2 prop started to run swayand at the time shen I cut the throttles read about 2500s and my engineer said that \$2 MLP was 53 inshess. I was applying decrease FRM on both \$I mad \$2 when I set throttless to were about 10 feet in air at 120 and had about 1300 feet of runsmay and a clear space off the end of the runways.

Just as we left the ground, the wear of the engines from being manyonbronized, was terrifits. I out the throttles and braided ship going off the end of the remaining the state of the remaining the ship went along on the ship went along on the ship went along on the ship went to the ship went along on the ship went to the ship went along on the ship went to the

WILLIAM P. MC CAPTHY.

CONFIDENTIAL

CONFIDENTIAL

on run up all engines and instruments charked CK. It McCarthy the file was riding right side as we were to fly #3 mosition and he shall be able to fly the wing botter from the right.

I made the take off and as we were going down the run way on the early 'part of the run, I checked the Manifold Pressure and RMMs and everything looked CK. Mace we were making 75 1PH I pulled the nose off and about that time I heard a prop out of syncronization. It McCarthy and the Sagineer ware taking care of the instruments and settines. Things seemed CK and the presumed the RPM on one engine might be set a little hith and continued the presumed that the LTM were off the ground at 120 and at that time LTM McCarthy decided to cut the power. He immediately settled on the ground and applied the brakes. He went off the end of the runway at about 50 MPH. The left gear gave way, the nose gear collapsed and we came to an immediate stop, During this time ILM VGCarthy cut the switches and attempted to rut the mixture controls in idle cut off. The crew was warmed to stand by for a crash. All the crew escaped injury. Four men went out the whist and 6 men out the top hatch. ILM CCCarthy came out the top that hatch last, The accident occurred at approximately 12:15.

ROBERT T MORFORD, lst Lt, AC, Co-Pilot. FLYING CONTROL
AAF 123 APO 558

RESTRICTED 50 MAY 1914

AC ICENT STATEMENT

AT 1210 HOURS, S-RE-J "C" 291, PILOTED BY

LT. ECCASTRY, TAKING OFF ON A PRACTICE MISSION,

CRASHED AT END OF RUIWAY OS AFTER HAVING GOTTEN.

ADOUT TET (10) FEST OFF THE GROUND. THE CRASH

WAS CAUGED BY TWO (P) RUNAWAY PROPS. FULL EXTENT

OF DAMAGE HOT ASCERT/ FIED. NO ONE WAS INJURED.

John M. Rollis F/LT., R.C.A.F., ELYLIS CONTROL OFFICER.

COPY: DIVIDED FLYING COUTROL FEED 1 () OUP CEEDATE S PILOT CONCERTED FILE

RESTRICTED DONFIDENTIAL

Alm135	7 June 4	J . 40m A			Leconomic	Doo of Othe I		ah a wila	ant Sou	dren (
Sta. 12			APO	558					ent Gro	ap (H)	
SHOULD LABOR		lam t	wne B	-24.5		Consc	lide t	d Vult		Die go	•
MAN & MANUT - THANKS	lerial Se.	01	4004 — No	AN & AND DOD	tel fin.	1	987 OR AC	0000007-1	yps, Global as	d Bertel Bo.	
	40291		=1830	-65A (N	38 . 80 l	E COLUMN	Police 1	too Bloss		Philos Plan	-
SHOULD LAST OF	non	10	16	er Mari	Die Die	and Book A		20125		120:25	_
727	рем			120:25		none					
1					Part 6	rooting, Bort	-				
Time in the	Countility on G	and	Describing Si	ares Beltetin	Bs. Pre	riseo Fellure	n Beerl	utow	lespector	to the or blood	Mostleo
man by Tay	Photographic		· ·			out b			70000		
1488 7 L	Cathood	الا	tretties			Pashago	Surre		Jones.		THELED
One Coly Ac	ILS, PROSABLI plicate Spaces /	Marra-Arek	Carres	ay Bapatibal	as service:	`		EX	PED	TE	
		wh 17 a	na le la	g off o			ed on	20 Mar	1011	nd 1 ad	
DETAILS		report	ts tha	t Nos.	1 and 2	prope!	llors	ren awa	y and o	ou ld	
		not be	cont	rolled.	Plans	begen	to mu	sh back	onto r	umay	1
				ot pull							
		on it	s bel	lly. No	person	nel we	re inj	ured an	d the p	lane	
										20110	
		did no	ot bus	m.							
		Upon !	napad	tion it							-
• •		Upon !	napad								-
CAUSE		Upon !	inspec walve	tion it							
	t TONS :	Upon dump	inspec walve	tion it							
IF COM FEIDAT		Upon dump dump dump None	inspectative m	stion it	125 P.	S.I. to	oo law	•	Gover	or 18	
		Upon dump dump dump None	inspectative m	tion it	125 P.	S.I. to	oo law	•	Gover	or 18	•
DESPOSITION		Upon dump dump dump None	inspectation was a ft as	ction it was set	125 P.	S.I. to	oo law	•	Gover	or 18	•
DESPOSITION	เ เหมือยาเร	Upbn i dump Unknot None	inspectation was a ft as	etion it was set	125 P.	S.I. to	oo law	•	Gover	or 18	•
DESPOSITION	NUMBERS BP-4376	Upbn dump dump dump dump dump dump dump dump	inspectative walve	etion it was set	125 P.	S.I. to	oo law	•	Gover	or 18	
DESPOSITION	NUMBERS BP-4376 BP-4377 BP-4375	Upbn-l dump Unknot None Aircr	inspectation walve	alvaged	125 P.	S.I. to	oo law	•	Gover	or 18	•
DESPOSITION	HUMBERS BP-4376 BP-4377	Upbn-l dump Unknot None Aircr	inspectation walve	etion it was set	125 P.	S.I. to	Depot,	Sta. 1	Govern	558	
DESPOSITION	NUMBERS BP-4376 BP-4377 BP-4375	Upbn-l dump Unknot None Aircr	inspectation walve	alvaged	125 P.	S.I. to	Depot,	Sta. 1	Govern	558	
DESPOSITION	NUMBERS BP-4376 BP-4377 BP-4375	Upbn-l dump Unknot None Aircr	inspectation walve	alvaged 120:25 120:25 120:25	125 P.	h Sub 1	Depot,	Sta. 1 ANCIS At Lt., gineer	Govern	558	
DESPOSITION	NUMBERS BP-4376 BP-4377 BP-4375	Upbn-l dump Unknot None Aircr	inspectation walve	alvaged 120:25 120:25 120:25	125 P.	h Sub 1	Depot,	Sta. 1 ANCIS At Lt., gineer	Govern	558	





