WAR DEPARTMENT

WAS DEPARTMENT RESTRICTED

U. S. ARMY AIR FORCES PERCET OF AIRCRAFT ACCUMENT

on AAF Ste. 123 (1) Plan AAF Sta. 505 (2) Paig 8 March, 1844 040 (DA 458th Bonh (H) 753rd Bomb (H) Armonager (4) Type and model Ath Air Porce Organization:

NAME Am Ponce on rim Spaven, George H. Zedseker, Hobert I 0-531028 2nd TA Sth AF No Thiury No 0 611276 2nd 7t Sth AF Ho/Injury Ho CP Keem.1. Poter (IDIT) 0-810990 2nd Tt AC Sth AP No/Thimry No 125 W Mortinson, James P. Cole, Cedrie C. Poster, Willia A. 0-692507 2nd T.t. 10 Sth AP No Thinky No 36721017 e/set. Sth AF No Thingy No IR 40 POS 26275501 T/Seta Sth AP No Thinky No 72 m 40 17159837 e/set. Ath AF No Thiury No UTG Poscher, Herman A. AC TOTAL Sth AP No /Injury No. f.TG heiding, Lawrence J. 16092460 9/3gt. *** 11029650 7 Cayford, Everett M. 2/3et. ir Sth AF No/Injury No 227 621.00 -40 Lieber, Leo (1841) 200 9/901/ RECEIVED

PERSONNET A

(24) AAF Sta.

who a Sitch Bomb(at 753rd P Present rating (as) Pilot (se 3-2-43

TOTED NO BOX FIRST PILOT HOURS (at the time of this accident) (28) This type. (42) Instrument time last 6 months

4001 (39) This model ASS (43) Instrument time last 30 days 27 - 45 (44) Night time last 6 months. (40) Last 90 days. (41) Total 79 -(45) Night time last 30 days AIRCRAFT DAMAGE

(49) LIST OF DAMAGED PARTS Rt. main landing gear, #3 and #4 engines and props, (AR) Aircraft. rt, wing panel, rt. flap, nose wheel, underside of (47) Engine(a) fuselage from sta. .1 to sta. 6.0

10/10 cloud cover at 1,000 ft., visibility 6 miles, wind North-(59) Weather at the time of accident . west 13 mph.

(51) Was the pilot flying on instrumen (52) Cleared from AAF Sta. 123

(48) Propeller(s)

its at the time of accident No (53) To Combat mission Combat mission 180 Combat mission (FF) Dilat's mission

(86) Nature of seeddent light tanks out of gas, #3 engine feathered, engines #1, #2 and #4 stopped on the base lag Approaching position was satisfactory with #4 engine ster expectedly and headed the sircraft for the landing caravan. To avoid hitting

the pilot stalled the plane and fell off to the right. / 3 - 4)

(57) Cause of secident All the engines cut out due to lack of gasoline in the sain fuel tanks.

RESTRICTED

20

DESCRIPTION OF ACCIDENT

(Brief narrative of accident. Include statement of responsibility and recommendations for action to prevent repetition)

Upon returning from a mission, pilot brought the plane down through an overcast on three engines and broke out over Watton. The pilot believing that the plane

was about out of gas, circled the field for a landing.

Pilot claimed that all the engines cut out on the base leg. On the approach, under 4 engine cut in and started to turn the plane to the left toward the carry, and the hangare. In order to world hitting the carryan, the pilot tried to pail the plane up and stalled out. The plane fell off to the right and wished out the right landing year, damaged number 3 and 4 engines and propellers, right wing, and the function of the plane was cateroized as El.

Although this forced landing resulting in the accident and damage described above was caused by the lack of fuel in the main fuel tanks immediately available for e.fire foregain, subsequent investigation revealed that the Tokio tanks contained

250 wallons of wasoling.

Fuel transfer pump was checked for operation, and as much as possible of the fuel transfer lines was visually inspected; there were no defects found

Attention is invited to the enclosed statement of 1/3gt while A. Foster reference, his efforts and proceedure in transferring gasoline from taking to-main. Proceedure followed by the 3gt was correct and would lead him to believe, as he did, that all gasoline had been transferred to the main takes.

The committee, finding no mechanical defects in the transfer eystem nor errors in the process of affecting transfer of the gasoline, was unable to place responsibility for the accident.



Signature Most of Signature Million Market Signature of S

753d Bombardsent Squadron (H) Office of the Operations Officer

13 March 1944

Report on Transferring Fuel on Ship # 729, 8 March 1944.

Before leaving the ground the orew-chief of this particular ship told me that the Bonkay booster pump, which is used for the "Tokio' tanks in transferring, puts out about 10 to 11 gallons personiunte. The pilot, Lt Spaven, and I decided to pump out approximately half of the gas.in these tanks to the mada cells before reaching the French coast. About two hours after taking-off and as we left the English coast, I transferred 15 minutes from the right "Tokio" tanks and put it in Bo 3 4 main cells. Then I pumped 15 minutes out of the left "Tokio" tanks and put that in Bo 1 4 2 main cells. Before transferring I checked the booster pump fuses, it was alright and then while transferring felt the lines and pump. These showed that the pump was putting out the gas. Being that the crew-chief said 10 gallons per minute, I figured the pump to have pumped approximately 150 gallons out of each "Tokio" tank.

On the way back, after we left the French coast, I transferred another 30 minutes on both tanks. This made a total of 50 minutes transfering from "Tokio" tanks to main cells. It was then that I figured that all the gas had been transferred. The second time trransferring I turned on the booster abut offs so that gas would register in the gauge. The other 150 gallons, I figured in the tanks registered on the guages.

Just to Bs on the eafs side when we developed trouble, I turned the "Tokio" selector valve to both on, and numbers 1, 2, 4 engines to tan't engine and cross feed, til-we reached the field, and on the approch. Then of turned the "Raico" selector to both off position. All the time I bransferred, the main booster pumps switches were off, and bombbay booster on.

Willis A. POSTER.
T/Sgt.
Willia Q. 3 other T/Sgt.

TRADOTTADORD Q 3RD STRATEGIC AIR DEPOT AAP 505 APO 635

Z-F-jab.

10 March 1944. Statement of 1ST LT LESLIE R. MATSON, Senier Flying Control Officer, on landing accident of Aircraft No. 41-26729, at Watton Airfield.

At 1723 hours, 8 March 1944, A B-24H, No. 41-28729, crashed at this field. The plane was piloted by 200 LT GROUGH H. SPAYEN and was returning from a combat mission. They were running very lew on gas and broke through the cloud base aliest over this field. While circling to make a normal approach on runway 11, all four (4) angines out on base leg. The plane reached the field but the pilot said that the No. 4 engine out in when they were almost on the ground and turned them at right angles to the runway and he was forced to stall in to avoid hitting the hangar. The right main landing gear was torn off, Hos. 3 and 4 engines and props damaged, right wing panel, nese gear, and lever part of fuselage from station 0.1 to 6.0 damaged. It is thought that the plane will have to be salvaged. He one was injured.

> LESLIE R. WATSON. let Lt. . Air Corns.

Senior Flying Control Officer.

goiffe àtlal

THIS IS ORIGINAL STATEMENT OF PILOT

August 202, Luce. Junior run nan or track

Surprist 200 H H Bur surprist of Lead rates

Luca for extend and trans surprist for the luca of the luca for the luca


1981 show fit bus four ways

In Sparen

This is true Statement of pilotr

HENRY R. MILLER JR. 1st Lt., AC





WA-288-178-3-44 505 (B24-H-128729)

