

(1) MISSION # 82 SORTIE ? yes A/C # 066 LETTER _____

A. CHECK LOADING LIST:

SQUADRON 753rd.

PILOT McCarthy W.P.
 CO-PILOT KOERNER G.P. R.W. GUNNER SINEGOS GUS
 NAVIGATOR WEILAND W.J. L.W. GUNNER KURTZ L.P.
 BOMBARDIER MERCER W.J. B.T. GUNNER MCCAIN J.K.
 RADIO OP. NIXON G.G. TAIL GUNNER APPLEBY G.C.
 TOP TURRET POLAKOFF L. PASSENGER & DUTY _____

B. CHECK FORMATION POSITIONS ON DIAGRAM.

(2) EARLY TURNBACK

A. BEFORE BEING DISPATCHED: TIME _____ PLACE _____
 REASON _____

B. AFTER BEING DISPATCHED: TIME _____ PLACE _____
 REASON _____

(3) NOT ATTACKING

REASON 10/10

(4) DEVIATION FROM BRIEFED ROUTE, IF ANY:(5) BOMBING DATA

TARGET _____ PT _____ ST _____ LR _____ OP _____

AIMING POINT _____ TIME _____ ALT. _____

HEADING _____ WIND DIR _____ WIND VEL. _____ I.A.S. _____

METHOD OF SIGHTING _____

BOMB LOAD _____ FUSES: (NOSE) _____ (TAIL) _____

BOMBS: (A) ON TARGET _____

(B) JETTISONED _____

(C) BROUGHT BACK all

RESULTS YOUR BOMBS: _____

RESULTS OTHER BOMBS: _____

CAMERA CARRIED? _____ TYPE _____ PHOTOS? _____ TIME _____

CAMERA OPERATED BY _____ HOMETOWN _____