

1108

458th 753rd 735 1108 6/2/44
 Group Sqdn A/E No. Letter Bomb-Load Date
 Position in Formation head high, right element 1st Sect 0820 1145
 Gun Pos. Take-off time Landing time
 PILOT SPAVEN, G.A. R/O COLE, C.C.
 CO-P ZEDEKER, R.L. GUNNER TEACHER, H
 NAV. KOWAL, P. GUNNER SCHIEDING,
 BOMB MORTINSON, J.M. GUNNER GLOVER, D.A.
 BOMB FOSTER, GUNNER LEIBER
 ENG. OBSERVER _____

1. ABORTIVE: Taking off _____ Dispatched Not attacking _____
 Point of turn-back and reason: 52°43' - 3°22' E. ~~Reason~~
supercharger on three engines #1 #3 & #4 went out.

2. BOMBS: _____ all
 (At target: No. size & type) (Jet. No. size type) (BB No. size type)
 Reason: _____

3. BOMBING ATTACK _____ PT ST LR OP _____
 Target

Aiming Point	Time	Altitude	Heading
--------------	------	----------	---------

Method of sighting, individual or other—describe _____

4. OBSERVED RESULTS OF BOMBING ATTACK: _____

5. ROUTE ~~IF~~ OTHER THAN BRIEFED: _____

6. WEATHER (only if it affected mission) As briefed

7. ENEMY FIGHTER OPPOSITION: No
No. E/A seen Types

Time Place Altitude

Colors or special markings Tactics employed (including rockets)

Time Place Altitude

Colors or special markings Tactics employed (including rockets)

Time Place Altitude

Colors or special markings Tactics employed (including rockets)

Counter measures and effectiveness

Effect of friendly fighter cover Description of new or unfamiliar

unfamiliar A/C or weapons (continue on reverse)

8. OBSERVED FIGHTER SUPPORT (Give no., type, time, place, height, combats with E/A:)

9. FLAK:

Time	Place <u>No</u>	Alt.	Intensity	Accuracy	Type of Fire

Any unusual characteristics

10. FRIENDLY A/C LOST OR IN DISTRESS (give full details, including position in formation)

11. OBSERVATIONS: Right out of beamer (1055) saw something appeared to be sinking in water. Saw ship appeared to be steaming toward it

12. PHOTOGRAPHY: Camera Carried? Yes Photos taken? No

13. CASUALTIES: (Name, position, injury, cause)?
No

14. DAMAGE TO A/C AND TECHNICAL FAILURES: No Interphone out
Tail turret out

15. CREW'S SUGGESTIONS AND COMMENTS: Had hard time getting equipment beams

S-2 OFFICER Christopher Harris Time Completed
1st Lt